

Environmental
Restoration
Contractor

ERC Team

Interoffice Memorandum



Job No. 22192

Written Response Required? No

Closes CCN: N/A

OU: 200-UP-1

TSD: N/A

ERA: N/A

Subject Code: 8630

TO: C. D. Wittreich, H9-12

DATE: January 9, 1996

45094

COPIES: See Below

FROM: Duane Jacques
Analytical Services/Field Services
H9-10/372-9400

SUBJECT: **200-UP-1 IRM IMPLEMENTATION SAMPLING, MONTHLY GROUNDWATER RESULTS, DECEMBER 1995, REV 0**

REFERENCES:

1. BHI, 1995a, *Field Screening (On-Site Measurements) Quality Assurance Plan*, BHI-EE-08, Bechtel Hanford, Inc., Richland, Washington.
2. BHI, 1995b, *Field Screening Procedures*, BHI-EE-05, Bechtel Hanford, Inc., Richland, Washington.
3. BHI, 1995, *200-UP-1 Field Screening Support Logbook*, EL-1277, Bechtel Hanford, Inc., Richland, Washington.
4. ChemChek, 1994, *Operation and Service Manual, Kinetic Phosphorescence Analyzer KPA-11*, ChemChek Instruments, Inc., Richland, Washington.

This data package contains field screening results for groundwater samples analyzed to support the 200-UP-1 IRM Implementation Sampling program. The Quality Assurance level for this work corresponds to QA-2 as specified in reference 1 (BHI 1995a). The samples were managed under SAF B96-003.

Attachment 1 contains Volatile Organic Compound (VOC) and total uranium results for groundwater samples collected to support the referenced project. The VOC results were generated using a Photovac 10S Plus portable gas chromatograph in accordance with Field Screening Procedure (FSP) 1.1, *Aqueous Headspace Analysis of Volatile Organic Compounds in Water* (BHI 1995b). Information concerning operation of the gas chromatograph is contained in the instrument logbook EL-1269.

The total uranium results were generated using a ChemChek KPA-11a Kinetic Phosphorescence Analyzer. The KPA-11a was calibrated and operated in accordance with the instrument operating manual (ChemChek 1994). Information concerning use of the ChemChek KPA-11a as well as preparation of VOC calibration standards and samples is contained in the referenced field logbook EL-1277, pages 49 through 51.

C. D. Wittreich, H9-12

Page 2

Please contact me if you have any questions on this information.



Duane Jacques, Scientist

QA Review by: Paul E. Duerksen

IDJ: idj

Attachments: Attachment 1. 200-UP-1 IRM Implementation Sampling, Monthly Groundwater Results, December 1995
Attachment 2. Sample Chain of Custody Sheets

Copies:

Analytical Services Project Files, X2-10, w/a
C. W. Denslow, H9-02, w/attachment 1 only
A. Hopkins, H9-11, w/attachment 1 only
J. A. Lerch, B1-35, w/a
D. A. Myers, H9-11, w/attachment 1 only
R. O. Mahood, H9-11, w/attachment 1 only
W. S. Thompson, N1-28, w/attachment 1 only
IDJ - File, w/attachment 1 only
BHI Document Control, H4-79, w/a

200-UP-1 IRM Implementation Sampling
Monthly Groundwater Results, December 1995
SAF B96-003

<i>Sample Location</i>	<i>HEIS Number</i>	<i>Sample Date</i>	<i>Analysis Date</i>	<i>Chloroform (µg/L)</i>	<i>Carbon TetraCl (µg/L)</i>	<i>TCE (µg/L)</i>	<i>Uranium (µg/L)</i>
299-W19-20	B0GZT4	1/2/96	1/3/96	NA	NA	NA	640
299-W19-20	B0GZT2	1/2/96	1/3/96	4.6	120	8.2	NA
299-W19-23	B0GZT6	1/2/96	1/3/96	NA	NA	NA	700
299-W19-23	B0GZT5	1/2/96	1/3/96	5.9	180	3.3	NA
299-W19-24	B0GZT8	1/2/96	1/3/96	NA	NA	NA	2650
299-W19-24	B0GZT7	1/2/96	1/3/96	5.6	130	5.0	NA
299-W19-37	B0GZB6	12/29/95	1/3/96	NA	NA	NA	3920
299-W19-37	B0GZB7	12/29/95	1/3/96	6.4	270	5.2	NA
Trip Blank	B0GZC3	12/29/95	1/3/96	< 4.0	< 2.0	< 2.0	NA
Trip Blank	B0GZT3	1/2/96	1/3/96	< 4.0	< 2.0	< 2.0	NA

NA - Not Analyzed

u - Value less than practical quantitation limit

VOA Instrument: Photovac 10S Plus GC, Serial # BJDG203

Method: 5 mL/min HP Air, 11.7 eV lamp, 250 uL injection

Logbook: Photovac Instrument Log, EL-1269, pg 10

Uranium Instrument: ChemChek KPA-11a, Serial # 9445050065

Method: Kinetic Phosphorescence

Logbook: 200-UP-1 Project Log, EL-1277, pgs 50 - 51

Uranium/

VOA Analyst:

I. B. Jacques
 I. B. Jacques

Data Turnaround

☐ Priority
☒ Normal

Collector <i>A. Rizzo / B. Kahlberg</i>	Company Contact C. D. Wittreich	Telephone (509) 372-9315
Project Designation OO-UP-1 IRM Implementation Sampling - Round 3	Sampling Location 200 West	SAF No. B96-003
Chest No.	Field Logbook No. <i>ERC-135</i>	Method of Shipment Hand Delivered
Shipped To Duane Jacques	Offsite Property No. NA	Bill of Lading/Air Bill No. NA
Possible Sample Hazards/Remarks	Preservation	HCI
	Type of Container	Gs
	No. of Container(s)	1
Special Handling and/or Storage Maintain samples between 2°C and 6°C.	Volume	40mL

SAMPLE ANALYSIS

Sample No.	Matrix*	Date Sampled	Time Sampled																
<i>299-419-20</i> 30 GZT2	W	1-2-96	1245	Y															
<i>219-419-20</i> 30 GZT3	W	1-2-96	0730	X	- Trip Blank														

CHAIN OF POSSESSION	Sign/Print Names	SPECIAL INSTRUCTIONS Hold all VOA samples at 4701-C until project is completed. Then deliver to Duane Jacques.	Matrix*
Relinquished By	Date/Time	Received By	Date/Time
<i>250-419-20</i> Relinquished By <i>R. Eubanks</i>	<i>1-3-96</i>	<i>CD Wittreich</i>	<i>1-3-96</i>
Relinquished By <i>D. Jacques</i>	<i>1-3-96</i>	<i>0840</i>	
Relinquished By	Date/Time	Received By	Date/Time
Relinquished By	Date/Time	Received By	Date/Time

Matrix*

S = Soil
 SE = Sediment
 SO = Solid
 SL = Sludge
 W = Water
 O = Oil
 A = Air
 DS = Drum Solids
 DL = Drum Liquids
 T = Tissue
 WI = Wipe
 L = Liquid
 V = Vegetation
 X = Other

LABORATORY SECTION	Received By	Title	Date/Time
FINAL SAMPLE DISPOSITION	Disposal Method	Disposed By	Date/Time

Bechtel Hanford, Inc.

CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST

Data Turnaround	
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

☐ Priority
☒ Normal

Collector A. Rizzo / B. Kitzberg		Company Contact C. D. Wittreich		Telephone (509) 372-9315		<input type="checkbox"/> Priority <input checked="" type="checkbox"/> Normal					
Project Designation 200-UP-1 IRM Implementation Sampling - Round 3		Sampling Location 200 West		SAF No. B96-003							
Ice Chest No.		Field Logbook No. EFL-1135		Method of Shipment Hand Delivered							
Shipped To Frank Gustafson		Offsite Property No. NA		Bill of Lading/Air Bill No. NA							
Possible Sample Hazards/Remarks		Preservation None									
		Type of Container P/G									
		No. of Container(s) 1									
Special Handling and/or Storage Maintain samples between 2°C and 6°C.		Volume 20mL									
SAMPLE ANALYSIS		Total Uranium									
Sample No.	Matrix*	Date Sampled	Time Sampled								
BO GZT4	W	1-2-96	1245	Y							
CHAIN OF POSSESSION		Sign/Print Names		SPECIAL INSTRUCTIONS						Matrix*	
Relinquished By		Date/Time 0750		Hold all Total Uranium samples at 4701-C until project is complete. Then deliver samples to Frank Gustafson.						S = Soil	
Received By		Date/Time 0750								SE = Sediment	
Relinquished By		Date/Time 1-3-96								SO = Solid	
Received By		Date/Time 1-3-96								SL = Sludge	
Relinquished By		Date/Time 1-3-96								W = Water	
Received By		Date/Time 0840								O = Oil	
Relinquished By		Date/Time								A = Air	
Received By		Date/Time								DS = Drum Solids	
Relinquished By		Date/Time								DL = Drum Liquids	
Received By		Date/Time								T = Tissue	
Relinquished By		Date/Time								WI = Wipe	
Received By		Date/Time								L = Liquid	
Relinquished By		Date/Time								V = Vegetation	
Received By		Date/Time								X = Other	
LABORATORY SECTION		Received By		Title		Date/Time					
FINAL SAMPLE DISPOSITION		Disposal Method		Disposed By		Date/Time					

Data Turnaround

☐ Priority☒ Normal

Collector <i>A. Rizzo / B. Fehlbach</i>	Company Contact C. D. Wittreich	Telephone (509) 372-9315
Project Designation OO-UP-1 IRM Implementation Sampling - Round 3	Sampling Location 200 West	SAF No. B96-003
Field Chest No.	Field Logbook No. <i>ERC-1135</i>	Method of Shipment Hand Delivered
Shipped To Duane Jacques	Offsite Property No. NA	Bill of Lading/Air Bill No. NA

Possible Sample Hazards/Remarks	Preservation	HCl																		
	Type of Container	Gs																		
	No. of Container(s)	1																		
	Volume	40mL																		
Special Handling and/or Storage Maintain samples between 2°C and 6°C.		VOA - TCL																		

SAMPLE ANALYSIS

Sample No.	Matrix*	Date Sampled	Time Sampled																	
299-47-23 30 GZT5	W	1-2-96	1510	Y																
30 NA	W																			

CHAIN OF POSSESSION	Sign/Print Names	SPECIAL INSTRUCTIONS Hold all VOA samples at 4701-C until project is completed. Then deliver to Duane Jacques.	Matrix* S = Soil SE = Sediment SO = Solid SL = Sludge W = Water O = Oil A = Air DS = Drum Solids DL = Drum Liquids T = Tissue WI = Wipe L = Liquid V = Vegetation X = Other
Relinquished By <i>P. F. D. / R. Fehlbach</i>	Date/Time 07-20	Received By <i>ERC</i>	Date/Time 07-20
Relinquished By <i>ERC</i>	Date/Time 1-3-96	Received By <i>D. Jacques</i>	Date/Time 1-3-96
Relinquished By <i>ERC</i>	Date/Time 1-3-96	Received By <i>ERC</i>	Date/Time 0840
Relinquished By	Date/Time	Received By	Date/Time

LABORATORY SECTION	Received By	Title	Date/Time
FINAL SAMPLE DISPOSITION	Disposal Method	Disposed By	Date/Time

Data Turnaround

☐ Priority☒ Normal

Collector <i>A. Rizzo / B. Fehle</i>	Company Contact C. D. Wittreich	Telephone (509) 372-9315
Project Designation OO-UP-1 IRM Implementation Sampling - Round 3	Sampling Location 200 West	SAF No. 896-003
Se Chest No.	Field Logbook No. <i>ERC-1135</i>	Method of Shipment Hand Delivered
Shipped To Frank Gustafson	Offsite Property No. NA	Bill of Lading/Air Bill No. NA

Possible Sample Hazards/Remarks	Preservation	None																		
	Type of Container	P/G																		
	No. of Container(s)	1																		
	Volume	20mL																		
Special Handling and/or Storage Maintain samples between 2°C and 6°C.	Total Uranium																			

SAMPLE ANALYSIS

Sample No.	Matrix*	Date Sampled	Time Sampled																	
<i>299-449-23</i> <i>00 GZT6</i>	W	<i>1-2-96</i>	<i>1510</i>	<i>6</i>																

CHAIN OF POSSESSION	Sign/Print Names	SPECIAL INSTRUCTIONS Hold all Total Uranium samples at 4701-C until project is complete. Then deliver samples to Frank Gustafson.	Matrix*
Relinquished By <i>R. Fehle</i>	Date/Time <i>0750</i>	Received By <i>ER</i>	Date/Time <i>0750</i>
Relinquished By <i>R. Fehle</i>	Date/Time <i>1/3/96</i>	Received By <i>D. Jacques</i>	Date/Time <i>1-3-96</i>
Relinquished By <i>R. Fehle</i>	Date/Time <i>1-3-96</i>	Received By <i>ERC</i>	Date/Time <i>0840</i>
Relinquished By	Date/Time	Received By	Date/Time

Matrix*

S = Soil
SE = Sediment
SO = Solid
SL = Sludge
W = Water
O = Oil
A = Air
DS = Drum Solids
DL = Drum Liquids
T = Tissue
WI = Wipe
L = Liquid
V = Vegetation
X = Other

LABORATORY SECTION	Received By	Title	Date/Time
FINAL SAMPLE DISPOSITION	Disposal Method	Disposed By	Date/Time

Data Turnaround

☐ Priority☒ Normal

Collector <i>A. Rizzo / B. Fenberg</i>	Company Contact C. D. Wittreich	Telephone (509) 372-9315
Project Designation 200-UP-1 IRM Implementation Sampling - Round 3	Sampling Location 200 West	SAF No. B96-003
ce Chest No.	Field Logbook No. <i>ERL-1135</i>	Method of Shipment Hand Delivered
Shipped To Duane Jacques	Offsite Property No. NA	Bill of Lading/Air Bill No. NA
Possible Sample Hazards/Remarks	Preservation	HCl
	Type of Container	Gs
	No. of Container(s)	1
Special Handling and/or Storage Maintain samples between 2°C and 6°C.	Volume	40mL

SAMPLE ANALYSIS

Sample No.	Matrix*	Date Sampled	Time Sampled																
<i>30 GZT7</i>	W	<i>1-2-96</i>	<i>1400</i>	<i>✓</i>															
<i>30 GZT7</i>	W	<i>NA</i>																	

CHAIN OF POSSESSION	Sign/Print Names	SPECIAL INSTRUCTIONS Hold all VOA samples at 4701-C until project is completed. Then deliver to Duane Jacques.	Matrix*
Relinquished By <i>30 GZT7</i>	Date/Time <i>0740</i>	Received By <i>ERC</i>	Date/Time <i>0750</i>
Relinquished By <i>30 GZT7</i>	Date/Time <i>1-3-96</i>	Received By <i>D. Jacques</i>	Date/Time <i>1-3-96</i>
Relinquished By <i>30 GZT7</i>	Date/Time <i>1-3-96</i>	Received By <i>ERC</i>	Date/Time <i>0840</i>
Relinquished By	Date/Time	Received By	Date/Time

Matrix*

- S = Soil
- SE = Sediment
- SO = Solid
- SL = Sludge
- W = Water
- O = Oil
- A = Air
- DS = Drum Solids
- DL = Drum Liquids
- T = Tissue
- WI = Wipe
- L = Liquid
- V = Vegetation
- X = Other

LABORATORY SECTION	Received By	Title	Date/Time
FINAL SAMPLE DISPOSITION	Disposal Method	Disposed By	Date/Time

Data Turnaround

☐ Priority☒ Normal

Collector <i>A. Rizzo / B. Fehlberg</i>	Company Contact C. D. Wittreich	Telephone (509) 372-9315
Project Designation OO-UP-1 IRM Implementation Sampling - Round 3	Sampling Location 200 West	SAF No. B96-003
Chest No.	Field Logbook No. <i>ERL-1135</i>	Method of Shipment Hand Delivered
Shipped To Frank Gustafson	Offsite Property No. NA	Bill of Lading/Air Bill No. NA

Possible Sample Hazards/Remarks	Preservation	None																		
	Type of Container	P/G																		
	No. of Container(s)	1																		
	Volume	20mL																		
Special Handling and/or Storage Maintain samples between 2°C and 6°C.		Total Uranium																		

SAMPLE ANALYSIS

Sample No.	Matrix*	Date Sampled	Time Sampled																	
<i>299-19-24</i> <i>10 GZT8</i>	W	<i>1-2-96</i>	<i>1400</i>	<i>Y</i>																

CHAIN OF POSSESSION	Sign/Print Names	SPECIAL INSTRUCTIONS Hold all Total Uranium samples at 4701-C until project is complete. Then deliver samples to Frank Gustafson.	Matrix* S = Soil SE = Sediment SO = Solid SL = Sludge W = Water O = Oil A = Air DS = Drum Solids DL = Drum Liquids T = Tissue WI = Wipe L = Liquid V = Vegetation X = Other
Relinquished By <i>299-19-24</i> <i>10 GZT8</i>	Date/Time <i>0750</i>	Received By <i>CD Wittreich</i>	Date/Time <i>0750</i>
Relinquished By <i>CD Wittreich</i>	Date/Time <i>01/3/96</i>	Received By <i>D. Jacques</i>	Date/Time <i>1-3-96</i>
Relinquished By <i>CD Wittreich</i>	Date/Time <i>1-3-96</i>	Received By <i>ER</i>	Date/Time <i>11/3/96</i> <i>0840</i>
Relinquished By	Date/Time	Received By	Date/Time

LABORATORY SECTION	Received By	Title	Date/Time
FINAL SAMPLE DISPOSITION	Disposal Method	Disposed By	Date/Time

Bechtel Hanford, Inc.

CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST

Page 1 of 1

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
1	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
2	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
3	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
4	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
5	1	2	3	4	5	6																																																																																														

☐ Priority
☒ Normal

Collector <i>A. Rizzo / B. Knicker</i>		Company Contact C. D. Wittreich		Telephone (509) 372-9315		<input type="checkbox"/> Priority <input checked="" type="checkbox"/> Normal	
Project Designation 200-UP-1 IRM Implementation Sampling - Round 3		Sampling Location 200 West		SAF No. B96-003			
Ice Chest No.		Field Logbook No. <i>ERC-1135</i>		Method of Shipment Hand Delivered			
Shipped To Frank Gustafson		Offsite Property No. NA		Bill of Lading/Air Bill No. NA			
Possible Sample Hazards/Remarks		Preservation	None				
		Type of Container	P/G				
		No. of Container(s)	1				
Special Handling and/or Storage Maintain samples between 2°C and 6°C.		Volume	20mL				
SAMPLE ANALYSIS			Total Uranium				
Sample No.	Matrix*	Date Sampled	Time Sampled				
BOGZB6	W	<i>12-29-95</i>	<i>1035</i>	<i>Y</i>			
CHAIN OF POSSESSION		Sign/Print Names		SPECIAL INSTRUCTIONS			Matrix*
Relinquished By		Date/Time	Received By	Hold all Total Uranium samples at 4701-C until project is complete. Then deliver samples to Frank Gustafson.			S = Soil
<i>Relinquished By IR Fahlberg</i>		<i>12/29/95</i>	<i>Received By B. Knicker</i>				SE = Sediment
<i>Relinquished By ERC</i>		<i>0840</i>	<i>Received By D. Jacobs</i>				SO = Solid
<i>Relinquished By B. Knicker</i>		<i>1-3-96</i>	<i>Received By ERC</i>				SL = Sludge
							W = Water
							O = Oil
							A = Air
							DS = Drum Solids
							DL = Drum Liquids
							T = Tissue
							WI = Wipe
							L = Liquid
							V = Vegetation
							X = Other
LABORATORY SECTION	Received By	Title		Date/Time			
FINAL SAMPLE DISPOSITION	Disposal Method	Disposed By		Date/Time			

Bechtel Hanford, Inc.

CHAIN OF CUSTODY/SAMPLE ANALYSIS REQUEST

Page 1 of 1

Data Turnaround

☐ Priority☒ Normal

Collector <i>A. Rizzo / B. Fehlbach</i>		Company Contact C. D. Wittreich			Telephone (509) 372-9315		
Project Designation 200-UP-1 IRM Implementation Sampling - Round 3		Sampling Location 200 West			SAF No. B96-003		
Ice Chest No.		Field Logbook No. <i>ERC-135</i>			Method of Shipment Hand Delivered		
Shipped To Duane Jacques		Offsite Property No. NA			Bill of Lading/Air Bill No. NA		
Possible Sample Hazards/Remarks		Preservation	HCl				
		Type of Container	Gs				
		No. of Container(s)	1				
Special Handling and/or Storage Maintain samples between 2°C and 6°C.		Volume	40mL				
SAMPLE ANALYSIS			VOA - TCL				
Sample No.	Matrix *	Date Sampled	Time Sampled				
BOGZB7	W	<i>12-29-95</i>	<i>1035</i>	<i>Y</i>			
BOGZC3	W	<i>12-29-95</i>	<i>0730</i>	<i>Y</i>			
CHAIN OF POSSESSION		Sign/Print Names			SPECIAL INSTRUCTIONS		
Relinquished By <i>FOR</i>		Date/Time <i>1230</i>	Received By <i>ERC</i>		Date/Time <i>1230</i>		
<i>B. Fehlbach</i>		<i>1-3-96</i>	<i>B. Fehlbach</i>		<i>12-29-95</i>		
Relinquished By <i>ERC</i>		Date/Time <i>0846</i>	Received By <i>D. Jacques</i>		Date/Time <i>1-3-96</i>		
<i>B. Fehlbach</i>		<i>1-3-96</i>	<i>Duane Jacques</i>		<i>0846</i>		
Relinquished By		Date/Time	Received By		Date/Time		
Relinquished By		Date/Time	Received By		Date/Time		
LABORATORY SECTION		Received By			Title		
FINAL SAMPLE DISPOSITION		Disposal Method			Disposed By		
					Date/Time		

Matrix*

S = Soil
 SE = Sediment
 SO = Solid
 SL = Sludge
 W = Water
 O = Oil
 A = Air
 DS = Drum Solids
 DL = Drum Liquids
 T = Tissue
 WI = Wipe
 L = Liquid
 V = Vegetation
 X = Other